





Parts needed to mount the DP-45-MOC fastener




Tools needed for mounting:


- Allen wrench

NOTE! A list of products corresponding with the selected accessories is available at klusdesign.com

1. Insert an assembled lighting fixture into the mounting bracket of the head (A).



2. Insert the rod into the mounting bracket of the head (B). It must press the power cable. Block the rod by tightening the pressure screw in the head with the Allen wrench.



3. Suspend the lighting fixture using a selected system.

