

Parts needed to mount the LINO extrusion

Extrusion (A)

End caps (B)

Cover (C)

LED strip (D)

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.KlusDesign.com

1. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Connect the power cable to the power source



2. Apply the double-sided tape to the extrusion (A), and attach the extrusion to the surface. Connect power