





Parts needed to mount the POR extrusion



Extrusion (A)



End caps (B)



Mounting insert (C)



Cover (D)




LED strip (E)


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at klusdesign.com

1. Install the LED strip (E), insert the cover (D) and the end cap (B).



2. Feed the power cable and put the mounting insert (C) in the railing.



3. Connect power, and then mount the extrusion.

